



State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:							
Company	lan McClain Associate Engineer						
OGM	Karl Houskeeper Environmental Scientist III						

Inspection Report

Permit Number:	C0150007		
Inspection Type:	COMPLETE		
Inspection Date:	Tuesday, September 08, 2009		
Start Date/Time:	9/8/2009 8:00:00 AM		
End Date/Time:	9/8/2009 2:00:00 PM		
Last Inspection:	Tuesday, August 11, 2009		

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Clear, Temp. 82 Deg. F. InspectionID Report Number: 2126

Accepted by: jhelfric

9/14/2009

Division Director

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO MID-CONTINENT REGION

Site: HIDDEN VALLEY MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

960.00	Total Permitted		
6.70	Total Disturbed		
6.70	Phase I		
	Phase II		
	Phase III		

Other

__ Federal ✓ Underground State Surface County ☐ Loadout Fee Processing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Reprocessing

Jaren Jorgensen, Consol, was present during the site visit.

Inspector's Si	anature:
----------------	----------

Karl Houskeeper, Environmental Scientist III

Date

Tuesday, September 08, 2009

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Inspection Type: COMPLETE

Inspection Date: Tuesday, September 08, 2009

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
- b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	V			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓	✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	V			
4.d	Hydrologic Balance: Water Monitoring	V			
4.e	Hydrologic Balance: Effluent Limitations	✓	✓		
5.	Explosives	✓	✓		
6.	Disposal of Excess Spoil, Fills, Benches	V	✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments	✓	✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	V			
11.	Contemporaneous Reclamation	V			
12.	Backfilling And Grading	✓			
13.	Revegetation	✓			
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.a	a Roads: Construction, Maintenance, Surfacing	✓			
16.b	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓			
19.	AVS Check	✓			
20.	Air Quality Permit	✓			
21.	Bonding and Insurance	✓		✓	
22.	Other	✓			

Inspection Continuation Sheet

Permit Number: C0150007 Inspection Type: COMPLETE

Inspection Date: Tuesday, September 08, 2009

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit C/015/007 was issued effective 01/29/2007 and expires 01/29/2012.

- -Certificate of Insurance policy number BOG 9377 215-05, issued 1/05/2009 and terminates 11/05/2009.
- -UPDES permit UTG-040026 effective 05/01/2008 and expires @ midnight 04/30/2013.

2. Signs and Markers

The mine ID sign is in place and contains the required information.

21. Bonding and Insurance

Surety Bond is posted for \$90,758